

Acme Township Development

Storm Water Run-Off

October 27, 2014

Made an on site visit today to the development in Acme Township. Inspected the site for soil erosion and for problem areas where sediment can leave the site. We had rainfall today and some site run off. This Acme Creek had some cloudiness in it. It was not as bad on October 14, 2014.

- Contractor needs to police a silt fence on the site to prevent further run-off from the site.
- Silt fence on the west side of the site has not still been fixed it was not toed in properly.
- Contractor was pumping water from westerly run off ditch and pumping up the hill and filtering it through the silt fence. Had no sediment bag on the end of the hose.
- Looked at basin the westerly basin was seeded, mulched, and had blanket on the slopes. It had a lot of standing water in it.
- The easterly basin had standing water in it a lot. It was seeded, mulched and blanketed. Overall in the basin you will not be able to get the grass to grow this year because of the season change.

Overall the contractor still needs to work with the Gourdie Fraser to get the site stabilized. The contractor does have some good measures in place to keep storm water from leaving the site but the biggest thing is to get the site stabilized.

Submitted By

Bernie Jacobson DEQ Number 10523