

**Acme Township Development  
Storm Water Run-Off**

December 10, 2014

**Observations:**

I made an onsite visit today to the new development in Acme Township. I inspected the corrective action that was listed on 12/8/2014(Thursday) with Mike Potter from Horizon Environmental. This site visit was requested by Horizon Environmental to verify the items in our 12/8/2014 inspection were corrected. The silt fence was taken a care holes were patched. All silt fences was toed in properly as per the manufacturer. Talked to Mike about one of the outlets by the Acme Creek where silt fence was taken down at a previous date and concerns about the upcoming snow fall of what will happen in the spring. Through this discussion contractor placed straw bales along the outside of the silt fence to prevent runoff from the site.

**Corrective Actions:**

- Contractor still needs to continue to monitor a silt fence on the site to prevent further run-off from the site.

Overall the contractor still needs to work with the Horizon Environmental to get the site stabilized. The contractor does have some good measures in place to keep storm water from leaving the site but the biggest thing is to get the site stabilized.

Submitted By,

Bernie Jacobson DEQ Number 10523