

Subject: VGT Inspection 10/15/14

Gentlemen,

I visited VGT today and report the following:

- 1) Elmer's crew was on-site repairing silt fences along western boundary. Soils super saturated on-site, more so than during any of my previous visits.
- 2) No discharge from Basin 1.
- 3) Basin 2 was discharging clay laden stormwater through grassed waterway conveyance and is reaching the Creek. See attached photos from M72 crossing and source area.
- 4) Creek running moderately cloudy at M-72 hwy crossing.
- 5) Justin Bragg, DEQ called a few minutes ago and plans to inspect the site today. He said that he has rec'd citizen complaints.
- 6) Seeds germinating better in all seeded areas with drier conditions and some sun today.

Full report to follow.



